

SSM 50212 - 2020-21 Corsair - 8F40 Transmission - Torque Converter Clutch Will Not Unlock Below 5 MPH (8 Km/h) - Built On Or Before 03-Mar-2021

Some 2020-2021 Corsair vehicles built on or before 03-Mar-2021 with the 8F40 transmission may have a torque converter clutch that will not release/unlock at below 5 mph (8 km/h). This may be due to an internal issue with the torque converter clutch (TCC). If this condition is present, install a new torque converter assembly. Refer to Workshop Manual (WSM), Section 307-01. For claiming, use causal part 7902 and applicable labor operations in Section 7 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2020 - 2021 CAR: TF CX483N CORSAIR